
11.0 WARRANTY

ELECTROMATIC Equipment Co., Inc. (ELECTROMATIC) warrants to the original purchaser that this product is of merchantable quality and confirms in kind and quality with the descriptions and specifications thereof. Product failure or malfunction arising out of any defect in workmanship or material in the product existing at the time of delivery thereof which manifests itself within one year from the sale of such product, shall be remedied by repair or replacement of such product, at ELECTROMATIC's option, except where unauthorized repair, disassembly, tampering, abuse or misapplication has taken place, as determined by ELECTROMATIC. All returns for warranty or non-warranty repairs and/or replacement must be authorized by ELECTROMATIC, in advance, with all repacking and shipping expenses to the address below to be borne by the purchaser.

THE FOREGOING WARRANTY IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE WARRANTY OF MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE OR APPLICATION. ELECTROMATIC SHALL NOT BE RESPONSIBLE NOR LIABLE FOR ANY CONSEQUENTIAL DAMAGE, OF ANY KIND OR NATURE, RESULTING FROM THE USE OF SUPPLIED EQUIPMENT, WHETHER SUCH DAMAGE OCCURS OR IS DISCOVERED BEFORE, UPON OR AFTER REPLACEMENT OR REPAIR, AND WHETHER OR NOT SUCH DAMAGE IS CAUSED BY MANUFACTURER'S OR SUPPLIER'S NEGLIGENCE WITHIN ONE YEAR FROM INVOICE DATE.

Some State jurisdictions or States do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation may not apply to you. The duration of any implied warranty, including, without limitation, fitness for any particular purpose and merchantability with respect to this product, is limited to the duration of the foregoing warranty. Some states do not allow limitations on how long an implied warranty lasts but, notwithstanding, this warranty, in the absence of such limitations, shall extend for one year from the date of invoice.

ELECTROMATIC Equipment Co., Inc.
600 Oakland Ave. Cedarhurst, NY 11516—USA
Tel: 1-800-645-4330/ Tel: 516-295-4300/ Fax: 516-295-4399

Every precaution has been taken in the preparation of this manual. Electromatic Equipment Co., Inc., assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of information contained herein. Any brand or product names mentioned herein are used for identification purposes only, and are trademarks or registered trademarks of their respective holders.

11.0 WARRANTY

ELECTROMATIC Equipment Co., Inc. (ELECTROMATIC) warrants to the original purchaser that this product is of merchantable quality and confirms in kind and quality with the descriptions and specifications thereof. Product failure or malfunction arising out of any defect in workmanship or material in the product existing at the time of delivery thereof which manifests itself within one year from the sale of such product, shall be remedied by repair or replacement of such product, at ELECTROMATIC's option, except where unauthorized repair, disassembly, tampering, abuse or misapplication has taken place, as determined by ELECTROMATIC. All returns for warranty or non-warranty repairs and/or replacement must be authorized by ELECTROMATIC, in advance, with all repacking and shipping expenses to the address below to be borne by the purchaser.

THE FOREGOING WARRANTY IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE WARRANTY OF MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE OR APPLICATION. ELECTROMATIC SHALL NOT BE RESPONSIBLE NOR LIABLE FOR ANY CONSEQUENTIAL DAMAGE, OF ANY KIND OR NATURE, RESULTING FROM THE USE OF SUPPLIED EQUIPMENT, WHETHER SUCH DAMAGE OCCURS OR IS DISCOVERED BEFORE, UPON OR AFTER REPLACEMENT OR REPAIR, AND WHETHER OR NOT SUCH DAMAGE IS CAUSED BY MANUFACTURER'S OR SUPPLIER'S NEGLIGENCE WITHIN ONE YEAR FROM INVOICE DATE.

Some State jurisdictions or States do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation may not apply to you. The duration of any implied warranty, including, without limitation, fitness for any particular purpose and merchantability with respect to this product, is limited to the duration of the foregoing warranty. Some states do not allow limitations on how long an implied warranty lasts but, notwithstanding, this warranty, in the absence of such limitations, shall extend for one year from the date of invoice.

ELECTROMATIC Equipment Co., Inc.
600 Oakland Ave. Cedarhurst, NY 11516—USA
Tel: 1-800-645-4330/ Tel: 516-295-4300/ Fax: 516-295-4399

Every precaution has been taken in the preparation of this manual. Electromatic Equipment Co., Inc., assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of information contained herein. Any brand or product names mentioned herein are used for identification purposes only, and are trademarks or registered trademarks of their respective holders.

TABLE OF CONTENTS

1.0	Introduction	2
2.0	Overview	3
	2.1 Gauge	
	2.2 Display	
	2.3 Complete Kit	
3.0	Basic Procedures	4
	3.1 Power	
	3.2 Selecting Units of Measure	
	3.3 Manually Setting the Measure Mode (DCFN version only)	
	3.4 Total Reset to Factory Defaults	
	3.5 Battery Replacement	
4.0	Taking Measurements Using Factory Calibration	7
5.0	Performing A ZERO Procedure (Custom Calibration)	8
	5.1 Checking Accuracy	
	5.2 Clearing a ZERO setting and restoring Factory Calibration	
6.0	Online statistics Display	10
	6.1 Deleting the Statistical Values	
7.0	Specifications	12
8.0	Resolution Table	13
9.0	Measuring Limits	14
10.0	Error Messages	15
11.0	Warranty	16

TABLE OF CONTENTS

1.0	Introduction	2
2.0	Overview	3
	2.1 Gauge	
	2.2 Display	
	2.3 Complete Kit	
3.0	Basic Procedures	4
	3.1 Power	
	3.2 Selecting Units of Measure	
	3.3 Manually Setting the Measure Mode (DCFN version only)	
	3.4 Total Reset to Factory Defaults	
	3.5 Battery Replacement	
4.0	Taking Measurements Using Factory Calibration	7
5.0	Performing A ZERO Procedure (Custom Calibration)	8
	5.1 Checking Accuracy	
	5.2 Clearing a ZERO setting and restoring Factory Calibration	
6.0	Online statistics Display	10
	6.1 Deleting the Statistical Values	
7.0	Specifications	12
8.0	Resolution Table	13
9.0	Measuring Limits	14
10.0	Error Messages	15
11.0	Warranty	16

1.0 INTRODUCTION

DCF-3000EZ-E = For measurement on steel / iron
DCFN-3000EZ-E = For measurements on steel / iron and
on non-ferrous metals

The Check•Line 3000EZ-E Series of coating thickness gauges provide accurate, non-destructive measurement of:

- All non-magnetic coatings, such as varnish, paint, enamel, chromium, copper, zinc, etc. on steel and iron. Measurements in the F mode (Ferrous) are carried out according to the Magnetic-Induction method.
- All electrically insulating coatings, such as varnish, paint, enamel on non-ferrous metals (aluminum, brass, stainless steel, etc). Measurements in the N mode (Non-ferrous) are carried out according to the Eddy-Current method.

NOTE: 3000EZ-E Series gauges operate in accordance with the following international standards related to coating thickness measurement:

Magnetic Induction

DIN EN ISO 2178, ASTM B499, DIN 50 982

Eddy-Current:

DIN EN ISO 2360, ASTM D1400

10.0 ERROR MESSAGES

- Error 1 =** The probe is too close to the metal
- Error 2 =** Error of gauge due to the effect of electro-magnetic interference fields
- Error 3 =** The probe is defective

For Technical Assistance contact:

Electromatic Equipment Company

Telephone: 1-800-645-4330 (USA & Canada)
1-516-295-4300

Fax: 1-516-295-4300

Email: info@checkline.com

1.0 INTRODUCTION

DCF-3000EZ-E = For measurement on steel / iron
DCFN-3000EZ-E = For measurements on steel / iron and
on non-ferrous metals

The Check•Line 3000EZ-E Series of coating thickness gauges provide accurate, non-destructive measurement of:

- All non-magnetic coatings, such as varnish, paint, enamel, chromium, copper, zinc, etc. on steel and iron. Measurements in the F mode (Ferrous) are carried out according to the Magnetic-Induction method.
- All electrically insulating coatings, such as varnish, paint, enamel on non-ferrous metals (aluminum, brass, stainless steel, etc). Measurements in the N mode (Non-ferrous) are carried out according to the Eddy-Current method.

NOTE: 3000EZ-E Series gauges operate in accordance with the following international standards related to coating thickness measurement:

Magnetic Induction

DIN EN ISO 2178, ASTM B499, DIN 50 982

Eddy-Current:

DIN EN ISO 2360, ASTM D1400

10.0 ERROR MESSAGES

- Error 1 =** The probe is too close to the metal
- Error 2 =** Error of gauge due to the effect of electro-magnetic interference fields
- Error 3 =** The probe is defective

For Technical Assistance contact:

Electromatic Equipment Company

Telephone: 1-800-645-4330 (USA & Canada)
1-516-295-4300

Fax: 1-516-295-4300


Email: info@checkline.com

9.0 MEASURING LIMITS

Minimum Radius for Convex Surfaces	0.2" (5mm)
Minimum Radius for Concave Surfaces	2" (50mm)
Minimum Headroom	2" (50mm)
Minimum Sample Diameter	0.4" (10mm)
Minimum Substrate Thickness - F	0.020 mils (0.5 mm)
Minimum Substrate Thickness - NFe	0.002 mils (0.05 mm)

2.0 OVERVIEW

2.1 Gauge




9.0 MEASURING LIMITS


Minimum Radius for Convex Surfaces	0.2" (5mm)
Minimum Radius for Concave Surfaces	2" (50mm)
Minimum Headroom	2" (50mm)
Minimum Sample Diameter	0.4" (10mm)
Minimum Substrate Thickness - F	0.020 mils (0.5 mm)
Minimum Substrate Thickness - NFe	0.002 mils (0.05 mm)

2.0 OVERVIEW

2.1 Gauge



2.3 Display



2.3 Complete Kit

3000EZ-E Series gauges are supplied as a complete kit, with gauge, plastic calibration shim, 2x AAA batteries, soft carrying pouch, manual and manufacturer's calibration certificate.


DCF models include a steel zero plate. DCFN models include steel and aluminum zero plates



8.0 RESOLUTION TABLE

Mils	
0.0 - 99.9 mils	0.1 mils
100.0 - 140.0 mils	0.2 mils
Microns (μm)	
0.0 - 999 μm	1 μm
1.000 - 2.498 mm	0.002 mm
2.500 - 3.500 mm	0.005 mm

2.3 Display



2.3 Complete Kit

3000EZ-E Series gauges are supplied as a complete kit, with gauge, plastic calibration shim, 2x AAA batteries, soft carrying pouch, manual and manufacturer's calibration certificate.

DCF models include a steel zero plate. DCFN models include steel and aluminum zero plates



8.0 RESOLUTION TABLE

Mils	
0.0 - 99.9 mils	0.1 mils
100.0 - 140.0 mils	0.2 mils
Microns (μm)	
0.0 - 999 μm	1 μm
1.000 - 2.498 mm	0.002 mm
2.500 - 3.500 mm	0.005 mm

7.0. SPECIFICATIONS

Range	
DCF, DCFN	<i>Ferrous:</i> 0.01 - 140.00 mils (0 - 3500 μ m)
DCFN Only	<i>Non-Ferrous:</i> 0.1 - 120.00 mils (3000 μ m)
Accuracy	± 0.1 mils (3 μ m) + 3% of reading
Resolution	Refer To Section 8.0
Display	Back-lit, 4-digit alphanumeric
Minimum Measuring Area	
0.4" x 0.4" (10mm x 10mm)	
Minimum Curvature Radius	
Concave: 2" (50mm) / Convex: 0.2" (5mm)	
Minimum Substrate Thickness	
DCF, DCFN	<i>Ferrous:</i> 0.020 mils (0.5mm)
DCFN Only	<i>Non-Ferrous:</i> 0.002 mils (0.05mm)
Calibration	Factory calibration, user-set zero calibration,
Statistics	Number of readings, mean value, standard deviation, maximum and minimum reading based on 99 readings (max).
Operating Temp.	32 °F to 122 °F (0 °C to 50 °C)
Surface Temp.	5 °F to 140 °F (-15 °C to 60 °C)
Storage Temp.	-4 °F to 140 °F (-20 °C to +60 °C)
Battery	2x AAA (1.5V)
Dimensions	4" x 2" x 1" (107mm x 50mm x 25mm)
Weight	3.2 oz (90 g)
Protection Class	IP 52 (proof against dust and dripping water)
Standards	DIN, ISO, ASTM, BS

7.0. SPECIFICATIONS

Range	
DCF, DCFN	<i>Ferrous:</i> 0.01 - 140.00 mils (0 - 3500 μ m)
DCFN Only	<i>Non-Ferrous:</i> 0.1 - 120.00 mils (3000 μ m)
Accuracy	± 0.1 mils (3 μ m) + 3% of reading
Resolution	Refer To Section 8.0
Display	Back-lit, 4-digit alphanumeric
Minimum Measuring Area	
0.4" x 0.4" (10mm x 10mm)	
Minimum Curvature Radius	
Concave: 2.0" (50mm) / Convex: 0.2" (5mm)	
Minimum Substrate Thickness	
DCF, DCFN	<i>Ferrous:</i> 0.020 mils (0.5mm)
DCFN Only	<i>Non-Ferrous:</i> 0.002 mils (0.05m)
Calibration	Factory calibration, user-set zero calibration,
Statistics	Number of readings, mean value, standard deviation, maximum and minimum reading based on 99 readings (max).
Operating Temp.	32 °F to 122 °F (0 °C to 50 °C)
Surface Temp.	5 °F to 140 °F (-15 °C to 60 °C)
Storage Temp.	-4 °F to 140 °F (-20 °C to +60 °C)
Battery	2x AAA (1.5V)
Dimensions	4" x 2" x 1" (107mm x 50mm x 25mm)
Weight	3.2 oz (90 g)
Protection Class	IP 52 (proof against dust and dripping water)
Standards	DIN, ISO, ASTM, BS

3.0 BASIC OPERATIONS

3.1 On/Off Switch

To turn the gauge on, press the **ON/OFF Switch** briefly (see photo on page 3). Press and hold the **ON/OFF Switch** for 2 seconds to turn the power off.

Note: The gauge will power off automatically after 90 seconds of non-use.

3.2 Selection of Measuring Units

1. Make sure the gauge is switched **OFF**.
2. Press and hold the **ZERO** and **STATS** keys simultaneously
3. While continuing to hold down the **ZERO** and **STATS** keys, turn the power **ON**.

3.3 Manually setting the measuring mode *DCFN-3000EZ-E Only*

In some cases, especially with varnish applied to zinc on steel, it is advisable to manually set the measuring mode—F mode (Ferrous) for measurements on steel/iron, N mode (Non-ferrous) for measurements on non-ferrous metals.

Setting the measurement mode

1. Turn the gauge on by pressing the **ON/OFF** switch.
2. Press the **ZERO** and **STATS** keys simultaneously to change the measuring mode. Each time the keys are pressed the mode will change.

The display will show the mode selected (see photo, page 4) using the following abbreviations:

3.0 BASIC OPERATIONS

3.1 On/Off Switch

To turn the gauge on, press the **ON/OFF Switch** briefly (see photo on page 3). Press and hold the **ON/OFF Switch** for 2 seconds to turn the power off.

Note: The gauge will power off automatically after 90 seconds of non-use.

3.2 Selection of Measuring Units

1. Make sure the gauge is switched **OFF**.
2. Press and hold the **ZERO** and **STATS** keys simultaneously
3. While continuing to hold down the **ZERO** and **STATS** keys, turn the power **ON**.

3.3 Manually setting the measuring mode *DCFN-3000EZ-E Only*

In some cases, especially with varnish applied to zinc on steel, it is advisable to manually set the measuring mode—F mode (Ferrous) for measurements on steel/iron, N mode (Non-ferrous) for measurements on non-ferrous metals.

Setting the measurement mode

1. Turn the gauge on by pressing the **ON/OFF** switch.
2. Press the **ZERO** and **STATS** keys simultaneously to change the measuring mode. Each time the keys are pressed the mode will change.

The display will show the mode selected (see photo, page 4) using the following abbreviations:

Ferr — indicates Ferrous Mode.

Non-Ferr — indicates Non-Ferrous Mode.


AUTO FN — indicates Auto-Select Mode.

3.4 Total Reset to Factory Defaults

1. Switch the gauge off.
2. Press and hold the **ZERO** key. At the same time, turn on the power using the **ON/OFF** switch
3. An acoustic signal will sound, all statistical values will be deleted and the factory settings μm , calibration, and AUTO FN (DCFN-3000EZ-E only) will be activated.

3.5 Battery Replacement

3000EZ-E gauges use 2x AAA alkaline batteries. When battery power becomes low, the **BATTERY INDICATOR** will begin to flash. The gauge will continue to operate, but the batteries should be replaced as soon as possible. When battery power is depleted, the Battery Indicator will remain on continuously, indicating that less than 60 seconds of power remains before the gauge will shut off.



6.1 Clearing the statistical values:

To clear the statistical values, momentarily press and release the **ON/OFF** switch. A value of zero will be shown in the number or measurements field "n" confirming that the stored statistical values have been cleared.

Ferr — indicates Ferrous Mode.

Non-Ferr — indicates Non-Ferrous Mode.


AUTO FN — indicates Auto-Select Mode.

3.4 Total Reset to Factory Defaults

1. Switch the gauge off.
2. Press and hold the **ZERO** key. At the same time, turn on the power using the **ON/OFF** switch
3. An acoustic signal will sound, all statistical values will be deleted and the factory settings μm , calibration, and AUTO FN (DCFN-3000EZ-E only) will be activated.

3.5 Battery Replacement

3000EZ-E gauges use 2x AAA alkaline batteries. When battery power becomes low, the **BATTERY INDICATOR** will begin to flash. The gauge will continue to operate, but the batteries should be replaced as soon as possible. When battery power is depleted, the Battery Indicator will remain on continuously, indicating that less than 60 seconds of power remains before the gauge will shut off.



6.1 Clearing the statistical values:

To clear the statistical values, momentarily press and release the **ON/OFF** switch. A value of zero will be shown in the number or measurements field "n" confirming that the stored statistical values have been cleared.

6.0. ONLINE STATISTICS DISPLAY

Every time a measurement is taken, a pair of statistical values appear in the lower part of the display, as shown at right.

For example:

$$n = 2 \quad x = 78\mu\text{m}$$

(n = number of measurements ; x = average)

Each time the **STATS** key is pressed, the number of measurements and a different statistical value will appear, allowing the user to easily scroll through statistics menu in the following sequence:

Press n = number of measurements; x = average

Press n = number of measurements s = standard deviation


Press n = number of measurements max = maximum reading

Press n = number of measurements min = minimum reading

You can pre-select a required pair of values by means of the **STATS** key, for example $n = 14$ $s = 3\mu\text{m}$, and have it displayed during the entire measurement data recording process.

Note: If no statistical values are saved, the display shows
 $n = 0$ $x = \mu\text{m}$

Important: If a series of measurements is meant to be statistically evaluated, the old statistical values must be deleted before starting a new series of measurements.



6.0. ONLINE STATISTICS DISPLAY

Every time a measurement is taken, a pair of statistical values appear in the lower part of the display, as shown at right.

For example:

$$n = 2 \quad x = 78\mu\text{m}$$

(n = number of measurements ; x = average)

Each time the **STATS** key is pressed, the number of measurements and a different statistical value will appear, allowing the user to easily scroll through statistics menu in the following sequence:

Press n = number of measurements; x = average

Press n = number of measurements s = standard deviation


Press n = number of measurements max = maximum reading

Press n = number of measurements min = minimum reading

You can pre-select a required pair of values by means of the **STATS** key, for example $n = 14$ $s = 3\mu\text{m}$, and have it displayed during the entire measurement data recording process.

Note: If no statistical values are saved, the display shows
 $n = 0$ $x = \mu\text{m}$

Important: If a series of measurements is meant to be statistically evaluated, the old statistical values must be deleted before starting a new series of measurements.



4.0 MEASURING USING FACTORY CALIBRATION


1. Press the **ON/OFF** switch to turn the gauge on.
2. If the **ZERO** icon *does not* appear in the upper left corner of the display, the preset factory calibration is activated.

If the **ZERO** icon does appear, it indicates that a Zero Procedure has been performed. See *Clearing a Zero Setting*, Section 5.2 before continuing.

3. Place the probe on the test object and read the measurement. Lift the probe off of the test object by at least 1 inch (3 cm) before taking another reading.

Note: Using the factory calibration, you can immediately carry out measurements on flat and slightly curved surfaces. **On strongly curved or rough parts it is recommended that a ZERO procedure be performed** (see section 5.0).

DCFN-3000EZ-E Only: The DCFN-3000EZ-E automatically recognizes whether the base material is a ferromagnetic steel or a non-ferrous metal and will display the correct reading.



4.0 MEASURING USING FACTORY CALIBRATION


1. Press the **ON/OFF** switch to turn the gauge on.
2. If the **ZERO** icon *does not* appear in the upper left corner of the display, the preset factory calibration is activated.

If the **ZERO** icon does appear, it indicates that a Zero Procedure has been performed. See *Clearing a Zero Setting*, Section 5.2 before continuing.

3. Place the probe on the test object and read the measurement. Lift the probe off of the test object by at least 1 inch (3 cm) before taking another reading.

Note: Using the factory calibration, you can immediately carry out measurements on flat and slightly curved surfaces. **On strongly curved or rough parts it is recommended that a ZERO procedure be performed** (see section 5.0).

DCFN-3000EZ-E Only: The DCFN-3000EZ-E automatically recognizes whether the base material is a ferromagnetic steel or a non-ferrous metal and will display the correct reading.



5.0 PERFORMING A ZERO PROCEDURE

To obtain more accurate measurements on strongly curved or rough parts, you should carry out the ZERO Procedure on a similar curved reference piece without coating.

1. Press the **ZERO** key. ZERO flashes in the display.
2. Place the probe on the bare surface several times. Lift the probe off of the surface by at least 1 inch (3 cm) between placements.
3. Press **ZERO** key again. The display shows ZERO
4. You can now carry out additional measurements.

Note: Zeroing is required if the convex radius of curvature

- is smaller than 30mm on steel parts,
- is smaller than 60mm on non-ferrous metal parts.


5.1 Checking accuracy

The foil standard included in the complete kit can be used together with the supplied zero plates (Fe or Al) to check the accuracy of the gauge. After zeroing, the measured thickness of the foil will be displayed within the tolerance of the foil plus the gauge accuracy..


5.2 Clearing a zero setting and restoring factory calibration

If the **ZERO** icon is shown on the display after switching on (see top photo below), a custom calibration is activated. To clear the custom setting:

1. Press the **ZERO** key twice. The **ZERO** icon disappears. The factory calibration is active. You can now take measurements using the factory calibration.



Custom calibration active



Custom calibration cleared

5.0 PERFORMING A ZERO PROCEDURE

To obtain more accurate measurements on strongly curved or rough parts, you should carry out the ZERO Procedure on a similar curved reference piece without coating.

1. Press the **ZERO** key. ZERO flashes in the display.
2. Place the probe on the bare surface several times. Lift the probe off of the surface by at least 1 inch (3 cm) between placements.
3. Press **ZERO** key again. The display shows ZERO
4. You can now carry out additional measurements.

Note: Zeroing is required if the convex radius of curvature

- is smaller than 30mm on steel parts,
- is smaller than 60mm on non-ferrous metal parts.


5.1 Checking accuracy

The foil standard included in the complete kit can be used together with the supplied zero plates (Fe or Al) to check the accuracy of the gauge. After zeroing, the measured thickness of the foil will be displayed within the tolerance of the foil plus the gauge accuracy..


5.2 Clearing a zero setting and restoring factory calibration

If the **ZERO** icon is shown on the display after switching on (see top photo below), a custom calibration is activated. To clear the custom setting:

1. Press the **ZERO** key twice. The **ZERO** icon disappears. The factory calibration is active. You can now take measurements using the factory calibration.



Custom calibration active



Custom calibration cleared

O1701

CHECK·LINE®
BY ELECTROMATIC

Coating Thickness Gauges DCF-3000EZ-E AND DCFN-3000EZ-E



Operating Instructions



ELECTROMATIC
EQUIPMENT CO., INC.

600 Oakland Ave., Cedarhurst, NY 11516-U.S.A.
TEL: 516-295-4300 • FAX: 516-295-4399

www.checkline.com

O1701

CHECK·LINE®
BY ELECTROMATIC

Coating Thickness Gauges DCF-3000EZ-E AND DCFN-3000EZ-E



Operating Instructions



ELECTROMATIC
EQUIPMENT CO., INC.

600 Oakland Ave., Cedarhurst, NY 11516-U.S.A.
TEL: 516-295-4300 • FAX: 516-295-4399

www.checkline.com